


Lake Tallavana Parcels




Lake Tallavana Contours




• Trees falling in lake



• Unstable littoral zone



 Land and Trees vanishing





Permit

- 10 year permit
- ~60 parcels
- 4248 yds fill
- 142 truck loads

- 2781 yds rock
- 93 truck loads



Common Carp




Erosion Control Blankets



Before

After



Rowlett Park Ditch, Tampa Original Conditions





Rowlett Park Ditch, Tampa Placing The C-350



Rowlett Park Ditch, Tampa After Sod Placement



Rowlett Park Ditch, Tampa

4 Days After Installation, a Major Storm Event Occurred


With No Erosion









Geoweb




LAKEWATCH, TP, Station 1




LAKEWATCH, TP, Station 4




LAKEWATCH, All Stations




LAKEWATCH, TN, Station 1




LAKEWATCH, TN, Station 4




LAKEWATCH, TN, All Stations




LAKEWATCH, Secchi, Station 1



LAKEWATCH, Secchi, Station 4




LAKEWATCH, TN/TP, Station 1



• TN/TP greater than 15, probably Nitrogen limited

LAKEWATCH, TN/TP, Station 4



• TN/TP greater than 15, probably Nitrogen limited

Mercury in Fish

- 1 ppm: do not eat
- 0.1 ppm: 2 fish meals per week
- New rules apply to men's cardiovascular
- All fish below 0.1 ppm

